


Accessible Restroom Approximate Location on Floor #	Automatic Building Entrance	Sidewalk Rating - Easy Little to No Elevation Change Typically Sidewalks	Sidewalk Rating - Difficult Varying Elevation Typically Steep Slopes or Stairs	Lactation Room Approximate Location on Floor #
Elevator or Chair Lift	Closed For Construction	Sidewalk Rating - Moderate Some Elevation Change Typically Ramps, Curb Cuts, and Uphill Sidewalks	Unisex Restroom Approximate Location on Floor #	



Project Title:
CAMPUS ACCESSIBILITY MAP

Sheet Title:
CORE CAMPUS

Drawn:
TAN

Checked:
JIS

Date:
12/12/2014

Scale:
NOT TO SCALE

Project Number:
1 OF 7

Drawn: SHEET NO.
1.1